



Photograph 13 - Offsite, intersection of Otisville Road and Route 211



Photograph 14 - View of stone house remnants



Photograph 15 - View of stone house remnants.



Photograph 16 - Ponded area south of house remnants



Photograph 17 - Offsite, debris between D&H Canal and railroad ROW



Photograph 18 - Offsite, debris between D&H Canal and railroad ROW



Photograph 19 - Offsite, debris between D&H Canal and railroad ROW



Photograph 20 - Woodchips, stone, lumber pile located on the property between railroad ROW and Basher Kill